

Operations Services Inc. 10281 Old US 27 South Gaylord, MI 49735 866.737.8361 www.operationsservices.com

Monthly Client Report for Higgins Lake Utilities Authority November 2022

To provide the Higgins Lake Utilities Authority with a summary of our activities for the month, Operations Services has prepared this report for your use. We welcome any suggestions to improve the information contained in these reports. Please contact us if you believe this report contains errors, or if you have any questions about it.

The Authority maintained compliance with all regulated parameters for the previous month.

FLOW AND UTILITY STATISTICS

LOW AND OTILITY O				
Parameters	2021	2022	Difference	
1st-7th Flow	37,200	32,687	-4,513	
8th-14th Flow	40,900	35,199	-5,701	
15th-21st Flow	35,600	32,199	-3,401	
22nd-31st Flow	42,500	37,550	-4,950	
Minimum Weekly Flow	35,600	32,199	-3,401	
Maximum Weekly Flow	42,500	37,550	-4,950	
Monthly Influent Total	156,200	137,632	-18,568	

2022 IRRIGATION PERFORMANCE

Parameters	Influent	Effluent	Difference
2021 Year to Date Totals	3,516,850	2,898,251	-618,599
2022 Year to Date Totals	3,454,155	3,001,929	-452,226
October Totals	137,632	0	+137,632

MONITOR WELL STATUS

Q4 samples were collected in November.

MONTHLY E-ONE ACTIVITY SUMMARY

- Operations Services received 6 E-One service requests for the month.
- 10815 W Higgins / Installed Station Riser
- 111 Midland / Buried Tray Cable
- 111 Breckenridge / Replaced Contactor
- 11990 Military / Replaced Contactor
- 124 Lincoln / Replaced Contactor
- 108 Mt Pleasant / Station Inspection Post Plumbing Work
- 2 Miss Dig Service Requests

STRATEGIC PLANNING

- Influent lift station maintenance in the fall to include solids/grit removal.
- Annual Influent & Effluent meters were calibrated. No issues noted.

OPERATIONS & MAINTENANCE

- Cell's 1 & 2 crossover piping continues to perform well concerning solids infiltration post work.
- Irrigation pump station and fields have been shut down and winterized.
- · Oil Change & Fuel Treatment on Snow Blower
- · Routine facility inspections completed.

CUMMINS BACK UP GENERATOR

• Monthly and weekly inspection and maintenance completed.

CONSIDERATIONS

Field 1 was tilled and reseeded. Will follow up with farmer on details.

OTHER NOTEWORTHY EVENTS OR ACTIVITIES

Fence repairs are ongoing.

If you have any questions regarding this report, please feel free to contact Operations Services at 866.737.8361

Operations Services, Inc.,

Phillip Corkins II

Project Manager / 989-619-9196

Higgins Lake Utility Authority 11371 Legion Camp Rd. Roscommon, MI 48653



November 2022

No Discharge

Wastewater Treatment Plant					Land Application			
D	Influent	Effluent		Efflue	nt Pumps		Field	Field
Α	Flow Meter	Flow Meter	Pump #1	Pump #2	Pump #3	Total	inches/day	inches/wk
Υ	Gallons	Gallons	Hours	Hours	Hours	Hours	applied	applied
11/1	5,940						0.000	
11/2	4,300						0.000	
11/3	4,300						0.000	
11/4	4,599						0.000	
11/5	4,599						0.000	
11/6	4,599						0.000	
11/7	4,350						0.000	0.000
11/8	4,350						0.000	
11/9	4,650						0.000	
11/10	4,650						0.000	
11/11	7,233						0.000	
11/12	7,233						0.000	
11/13	7,233						0.000	
11/14	4,200						0.000	0.000
11/15	4,200						0.000	
11/16	4,200			1981			0.000	
11/17	5,499						0.000	
11/18	4,900						0.000	
11/19	4,900						0.000	
11/20	4,900						0.000	
11/21	3,600						0.000	0.000
11/22	3,600						0.000	
11/23	4,920						0.000	
11/24	4,920						0.000	
11/25	4,920					ene en de se de de de	0.000	
11/26	4,920						0.000	
11/27	4,920						0.000	
11/28	3,250						0.000	0.000
11/29	3,050						0.000	
11/30	3,050						0.000	
Total	141,985						0.000	0.000
Maximum	7,233						0.000	0.000
Minimum	3,050						0.000	0.000
Average	4,733						0.000	0.000